



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 14, 2007

Supervisor RRH

Mine Name: Lakeside Mountain Limestone Quarry
Operator Name: Chemical Lime Co. of Arizona

Permit number: M/045/038
Inspection Date: October 24, 2006
Time: 9:00 am

Inspector(s): Lynn Kunzler, DOGM

Other Participants: None

Mine Status: Proposed.

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Check Status of Proposed Operation

Inspection Summary:

The LMO for this site was received December 16, 1991 and was never approved. As per comments on database, made on June 26, 2000, there was no disturbance and the permit fee (for a SMO) was being submitted to keep file active. This inspection verified that there was no mining related disturbances in this area.

Conclusions and Recommendations:

It is recommended that this file be closed (it is marked reclaimed - 1997) on the database. Since that operation never received final approval, it is quite likely that the NOI would need to be updated prior to activation of this site, and a reclamation surety would need to be calculated, submitted and approved.

Inspector's Signature

LK:pb

O:\M045-Tooele\M0450038-LakesideMountain\inspections\insp-10242006.doc